CROSSBAR DIAL SYSTEM

ILLUSTRATIONS OF CROSSBAR EQUIPMENT

BELL TELEPHONE LABORATORIES, INC.
SYSTEMS DEVELOPMENT DEPARTMENT
463 WEST STREET
NEW YORK CITY

(ISSUED FOR TRAINING PURPOSES ONLY)




Fig. 1 - Line Link Frame with Three Primary Bays




Fig. 2 - Subscriber Sender Link, District Junctor and District Link Frames (From Left to Right)




Fig. 3 - Subscriber Sender Unit



Fig. 4 - Subscriber Sender Frame




Fig. 5 - Originating Marker Connector Frame




Fig. 6 - Originating Marker Frame - Showing Originating Bay and Route Relay Bay




Fig. 7 - Line Junctor Grouping Frame




Fig. 8 - Office Link Frame




Fig. 9 - Terminating Sender Link, Incoming Trunk and Incoming Link Frames (From Left to Right)



Fig. 10 - Terminating and "B" Sender Frame






Fig. 11 - Full Selector Sender Unit



Casing Doors Closed



Casing Doors Open

Fig. 12 - Terminating Marker Frame




Fig. 13 - Number Group Connector Frame



Fig. 14 - Block Relay Frame




Fig. 15 - Line Choice Connector Frame




Fig. 16 - Line Junctor Connector Frame




Fig. 17 - Line Distributing Frame




Fig. 18 - Maintenance Center - Originating Sender Test, Sender Make Busy, Originating Trouble Indicator, Terminating Trouble Indicator and Incoming Trunk Test Frames (From Left to Right)




Fig. 19 - Miscellaneous Relay Rack - Apparatus Side




Fig. 20 - Miscellaneous Relay Rack - Wiring Side




Fig. 21 - General View of Main Cross Aisle, Showing Conduit and Power Feeders



Fig. 22 - General View of Cross Aisle




Fig. 23 - "A" Switchboard - 8, 8-1/2" Panel Section - 6'-2" High

